

FIG.1











FIG.










*FIG.7* 







FIG.9







FIG.11


*63e* 

63c



63;Locking Arm

FIG.12



Art Unit No. Unknown Replacement Sheet

FIG.13




FIG.14




FIG.15








FIG.16




















FIG.23




FIG.24




FIG.25

